




JEWELRY SAMPLE REQUIREMENT ESTIMATE GUIDE

To help customers to provide sufficient samples for testing the following guides are provided:


Necklace/Bracelet	1 Item
Earring	2 Pairs
Ring	1 Item

SURFACE COATING REQUIREMENT GUIDE

Bead Coatings	5mm:	20 Beads	
	10mm:	10 Beads	

EPOXY COATINGS: 

Epoxy Coatings the size area referenced above is for each separate color

PAINT COATINGS: 

PAINT Coatings the size area referenced above is for each separate color